Mathey Associates
ARCHITECTS
574 W. San Francisco St. Santa Fe, NM 87501
505/986-9854 matheyarchitecture@gmail.com

To: Historical Preservation Division
City of Santa Fe, NM

July 2, 2026

Re: Status review of structures at 1545 Upper Canyon Rd.

Good afternoon,

I wish to initiate a review of the historical status of two structures located at 1545 Upper Canyon Rd. in the cityôs Eastside historic district. The property is approximately 1.35 acres with an existing residence and detached garage/office. I believe construction of the house began in the 1950ôs but it has been remodeled several times through the 80ôs and the garage was constructed probably in the late 50ôs or in the 60ôs.

The property is currently designated as non-contributing in historical status but I was informed that this needs to be confirmed.

I am the authorized agent for the review as shown on the signed application.

Thank you, I look forward to working with you on this process.

Courtenay Mathey

HISTORIC PRESERVATION DIVISION PRE-APPLICATION REQUEST

PROPERTY OWNER(S) INFORMATION

Name (First, Last): Cyndy Lynch

Address: 1545 Upper Canyon Rd.
Street Address | Suite/Unit #

Santa Fe | NM | 87501
City | State | ZIP Code

Phone: 505/695.5749 | E-mail Address: clynchsf@aol.com

APPLICANT/AGENT INFORMATION (IF DIFFERENT FROM OWNER)

Name (First, Last): Courtenay Mathey, Architect

Address: 574 W. San Francisco St
Street Address | Suite/Unit #

Santa Fe | NM | 87501
City | State | ZIP Code

Phone: 505/986.9854 | E-mail Address: matheyarchitecture@gmail.com

APPLICATION DETAILS

Estimated Construction Cost: Unknown

Existing Square Feet: +/- 2500sf

Proposed Square Feet: Unknown

Proposed Work: Historic Status Review

AFFIDAVIT AUTHORIZING AGENT/APPLICANT (SIGNATURE REQUIRED)

I am/We are the owner(s) and record title holder(s) of the property located at: 1545 Upper Canyon Rd.


I/we authorize Courtenay Mathey to act as my/our agent to execute this application.

Signed: X Cyndy Lynch Date: 6/24/2026

Signed: Date:

915-3

Plat (AMENDED) showing a Boundary Survey (re-plat) of a tract of land lying within Projected Section 20, Township 17 North, Range 10 East, N.M.P.M., located within the City of Santa Fe, County of Santa Fe, State of New Mexico.



Vicinity Map * Not To Scale

Surveyor's Notes


1. No obstract of title, nor results of title searches were furnished the surveyor. There may exist other documents of record that would affect this parcel.
2. Date of field work: November 25, 2020 and February 1, 2021.
3. Basis of Bearing = Global Positioning Observations, Geodetic North, WGS 84 rotated to N64°01'00"W (L4) as per Reference Document no. 2.

Reference Documents

1. Warranty Deed (Joint Tenants) John Lynch and Frances M. Lynch to William Lynch and Angie L. Lynch, instrument no. 249,334.
2. Plat of Survey entitled, "A PLAT OF SURVEY FOR WILLIAM LYNCH WARD No.1", prepared by George Rivera, Plat Book 8, Page 205A, Instrument no. 248,558.
3. Plat of Survey entitled, "Boundary Survey Plat for David S. and Pam Fleischaker On Tract 1...", prepared by SIERRA LAND SURVEYING, INC., Plat Book 710, Page 002.
4. Plat of survey entitled, "LANDS SURVEYED FOR BERNADINO & TOBIAS LUJAN WARD NO. 1 SANTA FE, NEW MEXICO", prepared by George Rivera, Plat Book 13, Page 40, Instrument no. 287,512.
5. All other documents shown as adjoining owner data.

Legend

- ◉ – Set 1/2" rebar w/orange plastic cap, N.M.P.S. No.12178
- ⊙ – Found & Used 1/2" iron pipe
- ⊠ – Found & Used 3/4" iron pipe
- ⊙ – Found 1/2" rebar w/yellow plastic cap, "Cooper 9052"
- Ⓢ – Sewer Manhole eop – Edge of Pavement) (– Gate
- ⌀ – Utility Pole |s| – Sewer Station Lift Pump
- —o—o— – Coyote Fence
- —x—x— – Barbwire Fence
- ( ) – Record Data from reference document no. 2.
- [ ] – Record Data from reference document no. 3.
- { } – Record Data from reference document no. 4.



LINE TABLE		
LINE	LENGTH	BEARING
L1	42.47' [42.56']	S16°09'32"E [N14°30'51"W]
L2	24.40' [24.40']	S52°19'32"E [N50°40'51"W]
L3	36.60' [36.58']	S60°08'32"E [N58°38'10"W]
L4	56.63' [56.39']	S64°02'50"E [N62°25'21"W]
L5	18.65' [18.69']	S70°43'05"E [N68°41'34"W]
L6	41.25' [41.26']	S26°03'43"E [N24°28'37"W]
L7	33.24' {33.24'}	N21°06'22"E {S21°07'W}
L8	52.00' {52.00'}	N18°19'46"E {S18°16'W}

GRAPHIC SCALE
40 0 20 40 80
(IN FEET)
1 inch = 40 ft.

INSTR#2038991

County of Santa Fe } SS
State of New Mexico }
I hereby certify that this instrument was filed for record on the 5 day of August A.D. 2024, at 3:26 o'clock p.m., and was duly recorded in Book of Plats, 915, Page 3 of the Records of Santa Fe County.
Witness my Hand and Seal of Office
Katherine E. Clark
County Clerk, Santa Fe County, N.M.

Deputy

COUNTY CLERK SANTA FE COUNTY NEW MEXICO

INDEXING INFORMATION FOR COUNTY CLERK
U.P.C. NO. 1-056-099-320-072
WILLIAM LYNCH & ANGIE L. LYNCH
SECTION 4, T.16N., R.13E., N.M.P.M.

Amended Certificate

I, Gerald A. Sandoval, New Mexico Professional Surveyor no. 12178, do hereby certify this this Boundary Survey plat, previously filed for record as Instrument no. 1942358, in Plat Book 873, Page 20, has been amended solely to correct the misidentification of the Sewer Station Lift Pump.

8-5-24

Gerald A. Sandoval
N.M.P.S. 12178

Date

GERALD A. SANDOVAL NEW MEXICO 12178 REGISTERED PROFESSIONAL SURVEYOR

CITY OF SANTA FE PUBLIC NOTICE

THE CITY OF SANTA FE HAS NOT REVIEWED THIS PLAT OF SURVEY BEFORE ITS FILING IN THE OFFICE OF THE COUNTY CLERK. THIS SURVEY IS BASED ON THOSE DOCUMENTS NOTED HEREON. CITY OF SANTA FE MUST APPROVE ALL DOCUMENTS SUBMITTED WITH APPLICATION FOR BUILDING PERMIT AND MAY REQUIRE ADDITIONAL DOCUMENTATION TO PROVE LEGAL LOT OF RECORD. THIS STATEMENT DOES NOT IN ANY WAY REPRESENT OFFICIAL APPROVAL OF THIS PLAT.

ZIA SURVEYS

Gerald A. Sandoval
N.M.P.S. No. 12178
Cell: (505)470-4654

P.O. BOX 1042
Abiquiu, New Mexico 87510
122C Jimenez St.
Santa Fe, New Mexico 87501


1557
1545
CANYON RD

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

Date of Form:

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:

Lynch Family Property
Former Lynch Fence Company

2. Location:

1545 Canyon Road
Downtown and Eastside Historic District --- Santa Fe

3. Local Reference Number:
Santa Fe ID: Old # - 05160094

4. County: Santa Fe
Parcel # 11459968

5. Property Type:
_x Buildings: 2
_x Structures: 3
__ Site __ Object

6. Date of Survey: August 7, 2026

7. Previous Survey Date(s):
_x June 30, 1983, Michael Belshaw
__ No:

8. Name of Project:
HDRB Status Evaluation

9. Lat/Long:
3535.6841341,-105.9033078



10. Photo Information: Jim Rodman, photographer. Photo 1: View of west (front) elevation. Camera facing northeast. August 7, 2026.

11. Brief Description of the Property:

The Lynch family property consists of two principal buildings: a residence and an office-workshop complex. They occupy a large parcel on the north side of Canyon Road, east of the Martinez-Rivera farm. Originally constructed c. 1946 as a two-bedroom rental, the residence was enlarged over the years to roughly 2,058 heated square feet, including additions made after 1978 (Fig. 1). The office-workshop was erected in the 1980s at the height of the Lynch Fence Company's business. Attached to the complex is a corrugated-metal shed of unknown vintage. Also on the site is an open, two-bay carport, erected after 1978. The residence and office-workshop are designated Non-Contributing to the Downtown and Eastside Historic District; the secondary structures have no status.

Continued on Page 5.

12. Who uses the property? Residence

13. Construction Date:
Date: Residence, c.1946; office-workshop building, early 1980s
_x_Known _x_ Estimated Source: newspaper accounts, aerial photographs and family memory

14. Setting:
__ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar
Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: **(Photos, drawing, footprint, etc., indicate north arrow when possible)**



Source: Office of the Santa Fe County Assessor
parcel lines may not be accurate

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
Architectural History Services
w/ Jim Rodman

For: Current owner, via Mathey & Associates Architects

18. Owner (if known) and other knowledgeable people:

Current owner: Lynch Family Trust

19. Is Property Endangered? **_x_ Unknown __ No __ Yes How?**

20. Significance to Current Community: **_x_ Unknown __ None __ Low __ Moderate __ High**
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
See Historical Overview.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? _x_ No __Yes
Why? See Evaluation of Historical Status

23. National or State Historic District: City of Santa Fe

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Significant __ Contributing _x_ Non-contributing: residence and office -workshop building _x: No Status: metal shed, carport, and coyote fence.
Per City of Santa Fe official designation map:

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa Fe:
Downtown and Eastside Historic District

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID: Old # - 05160094
Lynch Family Property Former Lynch Fence Company	1545 Canyon Road Downtown and Eastside Historic District – Santa Fe	4. County: Santa Fe
		5. Date of Survey: August 7, 2026

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

_x_Adobe __ Brick __ Composition _x_ Concrete: Block

__ Concrete: Cast Stone __Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove _x_ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
_x_ Not visible __ None
__ At Grade __Raised:
Materials: _x_ Concrete: __Stone
Other:
Notes

9. Roof: __ N/A

Shape: _x_Flat __Gabled
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _x_Asphalt
__ Earth
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam__ Metal: V- Crimp: Red Panel
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Window Types Residence and Office Workshop Building

Operation	Material	Glazing	Number
Casement	Steel	3-3 I 2T	2
Casement	Wood or Metal	1-1	1
Casement	Vinyl	1-1	3
Double-Hung	Aluminum	1/1 w/ 6/6 grid	5
Sash	Wood	4	1
Sliding	Vinyl	1-1	8

Note: Based on visibility and access during survey

11. Door Types Residence and Office Workshop Building

Type	Style	Material	Number
Single-Leaf	8-panel	Wood	1
Single-Leaf	Altered	Wood	1
Single-Leaf	3-light over 4-panel	Wood	1
Single-Leaf	Oval light	Wood	1
Single-Leaf	10-light	Wood	2
Single-Leaf	2-light	Metal	1

12. Chimneys 2; corner and exterior stuccoed

13. Porches _x_ N/A
Type: _x_ Entry __Partial-Width __x Full-Width: altered __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications
Residence
#1 Date: 1961; block addition to north elevation; family recollection and visual and material evidence
#2 Date: 1970-71; carport and addition across south (front) elevation, including enclosure of original portal; family recollection; aerial photographs, and visual and material evidence
#3 Date: post-1978; addition at northeast corner; aerial photographs and visual and material evidence
#4 Date: Unclear, recent past; wholesale replacement of windows and doors; visual and material evidence

HCPI Detail Form (FORM 2) *(Continued from other side)*

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: _x_ Other: Vernacular

17. Documents Available and Their Locations

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605
https://www.santafenm.gov/land-use/historic-preservation


Archaeological Records Management Section
Laboratory of Anthropology
708 Camino Lejo
Santa Fe, NM 87501
(505) 476-1320
https://nmhistoricpreservation.org/arms.html

S I T E:

18. Attached or Associated Properties

Are associated properties eligible for listing: N/A

19.Site Plan: Portion of 2024 survey plat map. Courtesy of Zia Surveys.



For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

Architectural Description Continued

Setting

The Lynch family property is located roughly a mile east of Canyon Road's intersection with Camino Cabra. The approximately 1.4-acre parcel lies south of the Santa Fe River, with its north edge overlooking the site of the former Breese Burner manufacturing plant. The land is level and was formerly used for agriculture. It remains mostly in a natural state with mature Siberian elms scattered across the property. Both buildings are served by large asphalt-surfaced parking areas. The house is landscaped with foundation plantings and shrubs.

Residence

The house is situated on a northwest-to-southeast axis, approximately 70 feet from the road. Its composite ground plan forms a roughly 45-foot-long rectangle incorporating a carport added to the historic front façade and several other additions (Photo 1). The original 1940s adobe building occupies the central portion of the rectangle. Additions at the north and south ends of the historic core are constructed of a combination of concrete block and frame. The various sections are visually unified by a continuous stucco finish. Most windows are modern vinyl units, except for two that may date to an earlier period of construction. All doors have been replaced.

West (Principal) Elevation

Facing the asphalt parking area, the long west elevation serves as the principal entrance to the house and reveals the building's several additions (Photo 1).

At the south end is a large, two-vehicle carport erected in the early 1970s (Photo 2; Fig. 1). The roughly 380-square-foot, shed-roof structure is timber-framed, with large vigas carrying the roof. The roof edge is finished with sheet-metal-clad fascia.

The west wall terminating the carport forms part of another addition made at approximately the same time. Finished with a brown-and-white dado pattern, the wall is fenestrated with sliding vinyl windows, a type used throughout the building, and contains a modern door covered by a security gate (Photos 3 & 4). The carport's north

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

wall incorporates what was originally a portal, enclosed to create a foyer (Photos 4 & 5). The carport, adjacent addition, and enclosure of the portal considerably altered the historic design and appearance of the original house.

Returning to the elevation's main plane is the remaining portion of the original wraparound portal (Photo 6). Raised above grade with a flagstone floor, it contains an entry door obscured by a security gate and an older metal or wood casement window (Photos 7 & 8). Moving north is a small four-light wood window, perhaps dating to the building's original construction.

The northernmost portion of the west elevation represents an addition constructed by John Lynch in 1961 (Photo 9). It is entered through a door approached by several flagstone steps leading to a radial landing (Photo 10). As with the other entrances to the house, the door is obscured by a security gate. The addition also contains a single sliding vinyl window. A short stuccoed chimney stack rises from the northwest corner.

North Elevation

The short north elevation comprises the 1961 addition at the west and another addition at the east that postdates 1978 (Photo 11). This accretion is expressed by an interior north-south parapet rising above the roof. At the center is an entry approached by concrete steps and sheltered by a pent canopy. It holds a modern door covered by a security gate. The entry is flanked by sliding vinyl windows.

East Elevation

The long east elevation reveals the several phases of the building's evolution (Photo 12). Beginning at the north is the post-1978 frame addition referenced above (Photo 13). It is fenestrated with one small vinyl window.

The middle portion incorporates the original house and the 1961 addition. The short section of the addition is taller, while the original section is lower and finished with a metal-fascia-clad overhang (Photo 14). At its base is a line of contrapared. Both sections are fenestrated with modern vinyl windows, including sliding and casement units.

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

The southernmost section represents the early 1970s addition (Photo 15). It is marked by a stout exterior stuccoed chimney and a metal-fascia-clad overhang.

South Elevation

The south elevation combines the previously mentioned early 1970s addition and the carport (Photo 16). The former is fenestrated with a large sliding vinyl window, while the latter is screened by wood lattice.

Office-Workshop Building

Situated approximately 32 feet northwest of the house is the former Lynch Fence Company office and workshop. Erected in the 1980s,[1] it comprises a roughly 1,312-square-foot, stucco-on-frame combined office-workshop building with an attached 654-square-foot carport (Photo 17).

South (Front) Elevation

The public façade includes a sheltered entry to the office, which is entered through a custom wood-panel door (Photo 18). Above the door is a stylized false lintel, a treatment repeated elsewhere on the building. Adjacent is a double-hung aluminum sash window with a 6/6 grid. This window type is used on three elevations of the building. The window is recessed several inches from the wall plane and framed by splayed stuccoed reveals. The remainder of the façade is given over to two vehicle bays fitted with paneled overhead doors (Photo 17).

West Elevation

The carport shelters the west elevation (Photo 19), which includes an older steel casement window (Photo 20) and a wood pedestrian door with its openings covered by painted plywood (Photo 21). This older fenestration, along with an older door and

[1] Cyndy Lynch, email to John W. Murphey, September 9, 2026. Family recollection places construction of the present building in 1980; a published 1985 building permit similarly records construction of a "garage with workshop" on the property. "Building Permits," *Santa Fe New Mexican*, March 30, 1985, B8.

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

window on the north elevation, was reportedly salvaged from a rental owned by William Lynch.[2]

North Elevation

Facing the river, the rear elevation is sheltered by an overhang constructed of older milled boards (Photos 22 & 25). The elevation includes a steel casement window (Photo 23), an older three-light wood-panel door (Photo 24), and a double-hung aluminum sash window with a 6/6 grid (Photo 25).

East Elevation

Facing the house, the east elevation presents a symmetrical arrangement of fenestration, consisting of three aluminum windows with 6/6 grids, each topped by a stylized false lintel (Photo 26).

Metal Shed

Attached to the carport—and perhaps helping to support it—is a small shed constructed of corrugated sheet metal (Photo 19). Its gable front faces south and contains two doors made of the same material. The west side has a shallow lean-to addition supported by cedar poles (Photo 27). The origin of the shed is unknown.[3]

Detached Carport/Storage

Placed along the east property line is an open, two-bay carport/storage structure made of steel. Based on aerial photographs, the structure postdates 1978 (Photo 28, Fig. 5).

South Fence and Gate

The south frontage of the property along Canyon Road is lined with an older coyote fence, with an opening containing what appears to be a non-historic steel vehicular

[2] Ibid.
[3] Ibid.

gate. Neither the fence nor gate appear in the 1983 HBI photograph for the property (Fig. 6).

Historical Overview

Upper Canyon

The upper Santa Fe River Valley, colloquially known as Upper Canyon, historically supported an agricultural landscape extending eastward from the settled town. Sheltered by the surrounding terrain and encompassing a relatively level floodplain, the valley was divided into farm plots associated with families holding land outside the town center. Corn, wheat, alfalfa, and other crops were cultivated on the valley floor, while orchards and smaller fields occupied terraces watered by acequias. The land containing the subject property formed part of this agricultural landscape. On a 1914 hydrographic map, it falls within a larger parcel owned by Hinijo Martinez and is shown primarily under cultivation in alfalfa (Fig. 2).

The property subsequently passed through the Trujillo-Lujan family. Carmen Trujillo's grandson, Tobias Lujan, eventually received a portion of the family's larger holding from his older brother, José Lujan.[4] José, who had moved into town, conveyed land to each of his younger brothers on the same day. The resulting parcels remained clustered along Canyon Road. Tobias established his residence next door to the subject property, at what is now 1525 Canyon Road, while his brother Bernardino built a house farther west, at 1523 Canyon Road.

Tobias worked as a pressman for the Southwest Publishing Company, printer of the *Santa Fe New Mexican*, while also working nights as a security guard.[5] During this period, Tobias and his wife, Gumecinda (also Gumicinda), appear to have developed another portion of their property immediately east of their residence. They built a small adobe house intended as a rental at what is now 1545 Canyon Road. Newspaper accounts indicate that the house was completed by 1946.

[4] Warranty Deed, Jose E. Lujan to Tobias Lujan, recorded July 11, 1928, Book 8, Page 24, Instrument # 1928035778, Santa Fe County, New Mexico.

[5] "Memory of Old Office Towel Kept Green at New Mexican Shop Fest at Bishop's Lodge," *Santa Fe New Mexican*, January 4, 1926, 6.

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

A Rental Property

Contemporary newspaper notices provide small glimpses of activity associated with the property during its first year. In 1946, classified advertisements tied to the address included a ranch hand seeking work[6] and an offer to sell a box of ammunition.

Its first stable tenant was Larry C. Huston, an architect employed by William Kruger who also operated his own nursery and landscape installation business. Newspaper advertisements indicate that Huston installed flagstone walks, garden walls, and what he advertised as "fancy fish pools."[7] He operated two nurseries nearby, at 1517 and 1590 Canyon Road, where he sold flowers, shrubs, and landscape trees.

Huston's father, Milton Huston, lived nearby at 1519 Canyon Road. The elder Huston had come to Santa Fe in the late 1930s to work with James L. Breese on the development of an oil-burning heater. Breese's residence and fabrication facility stood downslope from the subject property, near the Santa Fe River.[8]

Larry Huston's occupancy of 1545 Canyon Road was relatively brief. The house was next leased by J. Hobson Bass, an Oklahoma drafting engineer. Like Milton Huston, Bass came to Santa Fe to work for the Breese Burners company,[9] and occupied the small adobe rental with his wife, Anna, and their four children. The last known renters in the 1950s were Ted Bonner, an Albuquerque land broker, and his wife, Catherine.

The Lynch Family

Family recollection holds that John Lynch had long been familiar with the property at 1545 Canyon Road. As a foreman for the water division of the Public Service Company of New Mexico, and later as a helper to artist Randall Davey, Lynch frequently traveled along Upper Canyon Road.[10] By the late 1950s, he had become attracted to the

[6] "22. Situations Wanted – I Want Work," *Santa Fe New Mexican*, May 21, 1946.
[7] "62 For Sale—Miscellaneous," *Santa Fe New Mexican*, Sept. 10, 1947, 9.
[8] John W. Murphey, *1469 Canyon Road, James L. Breese, Jr. Residence, Santa Fe, Santa Fe County, New Mexico*, New Mexico Historic Cultural Properties Inventory 1 & 2, prepared for Lorn Tryk Architects PC, December 23, 2018, 8 and 12.
[9] "J. Hobson Bass Services Held," *Santa Fe New Mexican*, Dec. 30, 1959, 9.
[10] Cyndy Lynch, telephone interview with John W. Murphey, August 12, 2026.

property, although family members recalled that he was bothered by its neglected, trash-strewn condition.

Born in San Francisco in 1897, Lynch came to Santa Fe as a child. Following the death of his father, tinsmith John William Lynch, in 1903,[11] his mother, Henrietta Davis Lynch, moved with John and his three brothers, Henry, Charles, and Edward, to Santa Fe in 1904.[12] A native of New Mexico, Henrietta established the family home in the 700 block of Canyon Road.

By 1961, discussions were evidently underway with the Lujan family for the acquisition of the property. In early May, John's son, William J. Lynch, hired a surveyor to define and record the parcel that would ultimately become his home.[13] On May 11, 1961, John Lynch received a deed to the property from Tobias and Gumecinda Lujan and José Lujan.[14] On the same day, John and his wife Frances conveyed the newly acquired property to their son William and his wife Angie.[15]

During the following two years, John Lynch enlarged the small rental house for William and his growing family. According to family recollection, he constructed an addition across the rear of the existing adobe dwelling, providing a new living room and bedroom.[16] Its construction provided needed living space for William and Angie, who were then renting a house in Glorieta with their five children. With the work completed, William, Angie, and their children moved into the remodeled and expanded Canyon Road house in November 1963.[17]

[11] "Deaths," *San Francisco Chronicle*, April 2, 1903, 12.
[12] Cyndy Lynch, telephone interview; California census and newspaper research.
[13] Survey Plat, William Lynch, recorded May 12, 1961, Book 8, Page 205, Instrument # 248558, Santa Fe County, New Mexico.
[14] Quitclaim Deed, Tobias and Gumicinda Lujan and José Lujan to John Lynch, recorded June 16, 1961, Book 179, Page 527, Instrument # 249333, Santa Fe County, New Mexico.
[15] Warranty Deed, John Lynch and Frances M. Lynch to William and Angie L. Lynch, recorded June 16, 1961, Book 179, Page 528, Instrument # 249334, Santa Fe County, New Mexico.
[16] Cyndy Lynch, telephone interview.
[17] Ibid.

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

The Lynch Fence Company

Born in Santa Fe in 1935, William J. Lynch grew up at the Lynch house in the 700 block of Canyon Road. He attended St. Michael's High School, where he excelled in business mathematics. After graduation, he held a variety of government jobs, including work as a Santa Fe city fireman. However, according to his daughter, Cyndy Lynch, he disliked working for other people.[18] His interest in operating his own business took tangible form in 1967 when he established the Lynch Fence Company. Although individual fence builders and installers operated in Santa Fe, independent businesses combining the sale of fencing materials with installation appear to have been less common.

William initially operated the company from the backyard of the family home at 1545 Canyon Road. An old, open-frame structure, no longer extant, provided storage for fencing materials. A 1969 aerial photograph captures the business in its early years, showing stacks of lumber and what appear to be piñon poles, along with a hauling truck and several pickup trucks (Fig. 4). The enterprise was very much a family operation. Angie Lynch handled the telephone and bookkeeping, while, over the years, three of the Lynch children worked for the company.[19]

The Lynch Fence Company gained prominence during the 1980s, when Santa Fe experienced substantial population growth and an influx of new residents seeking materials associated with the city's increasingly popular regional and rustic aesthetic. Although the company supplied conventional board and chain-link fencing, an increasingly important product was the vertical pole fence constructed from latillas that became widely known as "coyote fencing."

The company gained wider visibility when it was identified as a source for this type of rustic fencing in Christine Mather and Sharon Woods's influential 1986 book *Santa Fe Style*. The exposure likely broadened the company's customer base at a time when the Santa Fe aesthetic was gaining national popularity. The company also sold piñon firewood, another product closely associated with newcomers to Santa Fe.

[18] Ibid.
[19] Ibid.

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

The success of the Lynch Fence Company led to further development of the property. In the early 1980s, William built an office and workshop for the business. The house also grew. During the 1970s and 1980s, the Lynches added several rooms and a carport that enclosed the long side of the original portal (Figs. 1 & 4-5). By then, the small rental house built in 1946 had become both the Lynch family home and the center of their business.

A Family Property Sustained

The Lynch Fence Company continued operating into the 21st century, although growing competition from fencing, landscaping, and building-supply businesses gradually reduced its market. Angie Lynch, the company's original bookkeeper, died in 2019, followed by William three years later. Their children, by then in their 50s and 60s and long involved in various aspects of the family enterprise, decided not to continue the business. The company closed in 2022, and its remaining fencing materials and equipment were sold.[20]

The property was put on the market, where it remained for about a year and a half. The family ultimately transferred the land and buildings under a trust to Cyndy Lynch, who had returned to Santa Fe in 1990 after living in San Francisco and later worked as the company's accountant.[21] She now resides at 1545 Canyon Road and manages the property, continuing the Lynch family's association with the site more than six decades after its acquisition. She plans to renovate the buildings for her own use.

[20] Ibid.

[21] Lynch, email to John W. Murphey.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

Evaluation of Historical Status

Residence

Portions of the original 1946 residence and its first addition remain but have been largely obscured by later additions. The 1970–71 carport and portal enclosure disfigured the original building and obscured its principal character-defining features. As a result, the residence no longer clearly communicates its original design or historic associations. These alterations, together with the near-wholesale replacement of its fenestration, have substantially diminished its historic integrity. Its cumulative historic appearance through 1976 does not represent a coherent period of architectural development or retain sufficient integrity to convey its historic character. The recommendation is to maintain the residence's Non-Contributing status.

Office-Workshop Building

The office-workshop building has been demonstrated to have been erected in the 1980s and, therefore, falls outside the period of significance and does not meet the minimum threshold for Contributing status. The recommendation is to maintain its Non-Contributing status.

Detached Carport/Storage

This building has been demonstrated to post-date 1978 and, therefore, does not meet the minimum threshold for Contributing status. The recommendation is to designate the structure as Non-Contributing.

South Fence and Gate

The origin and date of construction of the south fence and gate are unknown. The gate is not present in the 1983 HBI survey photograph, and the fencing visible in the image is not of the present coyote-fence type. The recommendation is to designate the structure as Non-Contributing.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

Illustrations




Figure 1: Building expansion based on aerial photographs and family memory.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**




Figure 2: 1914 property boundary. State Engineer's Office, "Santa Fe Hydrological Survey," [series of maps] (Santa Fe: State Engineer's Office, 1914 (1919), Sheet 8.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Figure 3: Small building on site circled. October 25, 1948, aerial photograph.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Figure 4: Open shed behind house circled. February 27, 1969, aerial photograph.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Figure 5: Site, as of 1978. September 11, 1978, aerial photograph.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Figure 6: June 30, 1983, HBI survey photograph. Michael Belshaw. Note different type of fencing east and west of entrance.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

Survey Photographs

(All images taken by Jim Rodman, on August 7, 2026, unless otherwise noted)

Residence



Photo 2: West elevation, south end. 1970-71 carport and addition at right. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 3: West elevation, south end. 1970-71 carport and addition. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 4: West elevation, south end. 1970-71 carport and addition. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 5: West elevation, south end. South wall of enclosed portal. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 6: West elevation, middle section. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 7: West elevation, middle section. Portal door. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 8: West elevation, middle section. Portal window. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 9: West elevation, north end. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 10: West elevation, north end. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 11: North elevation. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 12: East elevation. Camera facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 13: East elevation. Camera facing southwest. Left, 1961; right, post-1978.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 14: East elevation, middle section. Camera facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**




Photo 15: East elevation, south end. Camera facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 16: South elevation. Camera facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

Office-Workshop Building



Photo 17: South elevation. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 18: South elevation, office entry. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 19: West elevation, carport, and shed. Camera facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**




Photo 20: West elevation, window. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 21: West elevation, window. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 22: North elevation. Camera facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 23: North elevation, south window. Camera facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 24: North elevation, center door. Camera facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 25: North elevation. Camera facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 26: East elevation. Camera facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**



Photo 27: Metal shed, west elevation. Camera facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Lynch Family Property** **Former Lynch Fence Company**	**2. Location:** **1545 Canyon Road** **Downtown and Eastside Historic District – Santa Fe**	**3. Local Reference Number:** **Santa Fe ID: Old # - 05160094** **4. County: Santa Fe** **5. Date of Survey: August 7, 2026**

Detached Carport/Storage



Photo 28: Detached Carport/Storage. Camera facing northeast. Cyndy Lynch, September 9, 2026.