NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1996

IDENTIFICATION

ADDRESS: 610 Agua Fria

OLD NUMBER: 05161 3605

BUILDING NAME:

UTM REFERENCE EASTING NORTHING

ZONE 12 13

LEGAL DESCRIPTION:

SANTA FE ID NUMBER: H 169.0

TNSP 17 (N) S RANGE 9 (E) W SEC 23 SE 1/4 SE 1/4

FIELD MAP Santa Fe
Historic Status Map 1996

DATE OF CONSTRUCTION:

_____ ESTIMATE by 1908 ACTUAL

SOURCE(S) Sanborn Map

BUILDING DATA

ARCHITECTURAL STYLE:

S-P / Terr.

USE:

HISTORIC: (residential)

OTHER _____

PRESENT: residential

OTHER commercial

Dos Casas Viejas Bed & Breakfast

SURROUNDINGS:

residential/commercial

RELATIONSHIP TO HISTORIC SURROUNDINGS:

X SIMILAR ____ NOT SIMILAR

ASSOCIATED BUILDINGS ON SITE:

X YES ____ NO

WHAT TYPE? Casitas, rear & to east.

IF INVENTORIED, LIST ID NUMBER(S)

_____

DEGREE OF REMODELING:

____ MINOR X MODERATE

____ MAJOR

EXPLAIN: New portal, stucco, windows, doors 1990.

OVERALL CONDITION:


X EXCELLENT ____ GOOD

____ FAIR ____ DETERIORATED

BUILDING THREATENED?


____ YES X NO

PHOTO



#24 North Elevation

SITE PLAN



SIGNIFICANCE

LISTED ON NATIONAL REGISTER OF HISTORIC PLACES?

X YES ____ NO ____ ELIGIBLE

X CONTRIBUTING ____ NON-CONTRIBUTING

LISTED ON STATE REGISTER OF CULTURAL PROPERTIES?

X YES ____ NO ____ ELIGIBLE

LOCAL DESIGNATION: Westside-Guadalupe HISTORIC DISTRICT

____ SIGNIFICANT X CONTRIBUTING ____ NON-CONTRIBUTING

LOCAL LANDMARK ____ YES X NO

SURVEYED 7/25/96 BY MJH


NEGATIVES WITH NMHPD ROLL # 4 NEG # 24 TO ____
5 # 13 & 14

ARCHITECTURAL FEATURES: STYLE, MATERIALS, AND CONDITION


ROOFS & DRAINS	Parapet, some red brick coping, roof slopes w. t[illegible] overhang, alum gutters/drain.
BUILDING WALLS	Tan stucco on dbl adobe.
FOUNDATIONS	Not visible — APPROX. HEIGHT (FT.) 13 ft.
DOORS All are replacement.	Wood Dutch 2 lights / 1 panel; Wood Fr. single, pr. & pr. w/ sidelights of same; Gates: both wood; w/ iron grille in top panel; At. Drive: Wood planks in steel frame
WINDOWS	Wood dhw. single & pr; Wood fixed; Wood Awning — All are replacements; White alum. screens
PORCHES OR PORTALES	Shed roof w/ roll roofing 1X10 decking. vigas, corbels, round columns set on sq. stuccoed base, floor is 2x6 cedar boardwalk.
ARCHITECTURAL DETAILS	dbl thickness adobe walls, some red brick coping, stucco bullnosed at fenestration. S-P portal, stepped parapet,
FENCES/WALLS	N: 7' st. on adobe wall. E: 6' st. on adobe or blk. wall W: 7'-8' coyote & 7' st. on adobe wall, same encloses lap pool.
SITE FEATURES	

OTHER/ COMMENTS A nice rehab of the property makes it less than significant in status, yet the massive irregular shape helps it to retain enough interity to be classified as contributing. Owners Michael & Susan Strijek have photos of the bldg. before renovation. They indicate that all new doors, windows, brick coping & stucco have been added in 1990, also a small addition at rear, & portal rebuilt. On King Map as Blk. 15 lot 4 mrs. Cecilia Ortiz.

ADDITIONAL PHOTOGRAPHS




#13 East Elevation




#14 South Elevation


AQUA FRIA
AQUA FRIA
DUDROW
WAGNER
GUADALUPE
MARY E. JAMES, PRESBYN MISSION SCHOOL
Located 600' N of Federal Bldg. See Sheet 4
VACANT
C. W. DUDROW WOOD YARD & WOOD SAWING
L. A. HUGHES, LUMBER YARD
C. W. DUDROW, LUMBER YARD
CARTWRIGHT-DAVIS CO. HAY WARE HO.
CONTINENTAL OIL CO OIL WARE HO
LEMP BREWING CO
LUMBER
LUMBER SHED
WARE HO.
COAL BIN
8" W. PIPE
Proposed 4" W. Pipe



NEW DOOR


NEW DOOR
AGUA FRIA


AGUA FRIA →
NEW DOOR


AGUA FRIA →
NEW DOOR HERE ↓


AGUA FRIA
NEW DOOR HERE


SIDE GARDEN WALL
NEW DOOR HERE



AGUA FRIA →
← NEW DOOR


AGUA FRIA →
NEW DOOR HERE ↓


AGUA FRIA
NEW DOOR HERE


SIDE GARDEN. WALL
NEW DOOR HERE


NEW DOOR


NEW DOOR
AGUA FRIA

169.3

building threatened?	surveyed	county	ID no.
yes	date 8/3/85 by HMW	SANTA FE	051613606

field map	number	UTM reference	easting	northing
SFHD # 7	606	zone 12 13		

location description: 610 1/2 AGUA FRIA

city/town: SANTA FE

land grant/reservation: ~~land grant/reservation~~


building name:

legal description: tnsp ___ N S range ___ E W sec ___ ¼ ¼

film roll	negative nos.	loc. of neg.
by SL no. SFHD #20	14	HPB



plan shape:



date of construction: 1912 — C. 1930's. estimate ___ actual

source:

use
present: residential
other:
historic: residential
other:

condition
___ excellent ✓ good
___ fair ___ deteriorating

degree of remodeling
✓ minor ___ moderate ___ major
describe:

style: NMUV.

foundation material: CONC.

wall material/surface: ADOBE / STUCCO

architectural features
SIDED RF TO E. BOXED WD EAVE.
12 LIGHT WD CASM'TS.
1 TRIP 3/1 WD CASM'T 1 TRIP 4/1 WD CASM'T.
1 FLANKED IS LIGHT SGL LF DOOR.
1 8 LIGHT SGL LF DOOR.
1 3 LIGHT SGL LF DOOR
SIMPLE FRAME PORCH ON REAR END.

comments
NOT ON KING'S, SF DIR UNCLEAR.
APPEARS TO HAVE GROWN N → S.

surroundings: RES.

relationship to surroundings
✓ similar ___ not similar

district potential
___ yes ___ no

significance
___ eligible ✓ of interest ___ none
if eligible, why? contrib.

associated buildings? ___ yes
what type?
CB GARAGE.
if inventoried, list ID nos.

see back? ___ yes