613 W. San Francisco

Total / 547.7


Count / 45

AVG / 12.17

Max 14'2"

10/8/26




613 W. San Francisco
Pitch 19
Flat 32
Total 51
37% pitch not Allowed
N GUADALUPE ST
PASEO DE PERALTA
W SAN FRANCISCO ST
VILLA ALEGRE ST
JIMENEZ ST
QUINTANA ST
ELENA ST
DURAN ST
DOLORES ST
CALLEJON TISNADO
W ALAMEDA ST

NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1996

IDENTIFICATION

ADDRESS: 613 W. San Francisco (NW corner at Candelario)

OLD ID NUMBER: 0516 3168

BUILDING NAME:

UTM REFERENCE EASTING NORTHING

ZONE 12 13

LEGAL DESCRIPTION:

SANTA FE ID NUMBER: H 3294

TNSP 17 (N) S RANGE 9 (E) W SEC 23 NE 1/4 SE 1/4

FIELD MAP Santa Fe Historic Status Map 1996

BUILDING DATA

DATE OF CONSTRUCTION:

_____ ESTIMATE by 1912 ACTUAL

SOURCE(S) J. Baca Blk 31 Lot 25 King Map

ARCHITECTURAL STYLE: N.M. Vernacular

USE:

HISTORIC: (residential)

OTHER _____

PRESENT: (residential)

OTHER _____

SURROUNDINGS: residential

RELATIONSHIP TO HISTORIC SURROUNDINGS:

X SIMILAR ___ NOT SIMILAR

ASSOCIATED BUILDINGS ON SITE:

X YES ___ NO

WHAT TYPE? storage

IF INVENTORIED, LIST ID NUMBER(S)

_____

DEGREE OF REMODELING:

___ MINOR X MODERATE

___ MAJOR windows replaced

EXPLAIN: roof not original but owner (60yrs plus) says it has been like that all his lifetime

OVERALL CONDITION:

___ EXCELLENT X GOOD

___ FAIR ___ DETERIORATED

BUILDING THREATENED?


___ YES X NO

PHOTO



#9 South Elevation & South end of East Elevation

SITE PLAN



SIGNIFICANCE

LISTED ON NATIONAL REGISTER OF HISTORIC PLACES?

X YES ___ NO ___ ELIGIBLE

X CONTRIBUTING ___ NON-CONTRIBUTING

LISTED ON STATE REGISTER OF CULTURAL PROPERTIES?

X YES ___ NO ___ ELIGIBLE

LOCAL DESIGNATION: Westside-Guadalupe HISTORIC DISTRICT

X SIGNIFICANT ___ CONTRIBUTING ___ NON-CONTRIBUTING

LOCAL LANDMARK ___ YES X NO

SURVEYED 5/21/96 BY MJH

NEGATIVES WITH NMHPD ROLL # 2 NEG # 8 TO 10

ARCHITECTURAL FEATURES: STYLE, MATERIALS, AND CONDITION

ROOFS & DRAINS	Offset gable of corrugated metal, propanel at rear.
BUILDING WALLS	Stucco, painted white, on adobe, front portion double adobe walls.
FOUNDATIONS	not visible — APPROX. HEIGHT (FT.) 14 ft
DOORS	Wood 3 lights 4 panels; Wood 1 light 4 panels; Wood 13 panel; Solid wood 3 lights. Wrought iron screen doors.
WINDOWS	Recessed aluminum sliding units flanked by wood shutters painted turquoise. 1 picture flanked w/sliding, as above. Wrought iron grilles.
PORCHES OR PORTALES	Gable roof extends out over front & rear porches, both have boxed ceilings, 4x4 posts, bancos extend the length of both, wrought iron balustrade, floor of concrete covered w/indoor-outdoor carpet.
ARCHITECTURAL DETAILS	Gable ends sheathed w/ seamed metal, recessed fenstration.
FENCES/WALLS	6' chain link fence & gates, covered w/vines. N. has 7' plank & hedge.
SITE FEATURES	
OTHER/ COMMENTS	At w. side is a storage shed of stucco on adobe, shed roof of corrugated metal pr. wd. 6 light casmt. windows. Sanborn maps do not cover this area.

ADDITIONAL PHOTOGRAPHS



#10 West Elevation & westend of South Elevation



#8 East Elevation

NEW MEXICO HISTORIC BUILDING INVENTORY FORM

H3294

building threatened? yes	surveyed date 8/85 by SL	county SANTA FE	ID no. 05163168
field map SFHD # 7	number 168	UTM reference zone 12 13	easting northing

location description: 613 W. San Francisco


city/town: SANTA FE

land grant/reservation: ~~land grant/reservation~~


building name:

legal description: tnsp___ N S range___ E W sec___ ¼ ¼

film roll by SL no. 5	negative nos. 34	loc. of neg. HPB



plan shape



date of construction: Pre '28 estimate ____ actual

source: directory old: (Pre 1912 Kings)

use
present ✓residential
other ____
historic ✓residential
other ____

condition
___excellent ___good
✓fair ___deteriorating

N.M. Vernacular

conc?

wall material/surface: adobe & ? / stucco

degree of remodeling
✓minor ✓moderate ___major
describe: added massing & roof

architectural features
- Off-set gable rf. of corrugat'd mtl. - extended eave & exposed rf. joists on S & conceal'd on N.; orig. vigas projecting on N under eave.; NW addition has lower rf. line which sheds to W w/ extend'd eave + conceal'd joists
- windows: reces'd alum. sliding; mtl casemt: ▯▯, 3'×4' (some w/ tourquoise shutters)
- doors: solid w/ 3 sm. lits

surroundings: residential

relationship to surroundings
✓similar ___not similar

district potential
✓yes ___no

significance
___eligible ✓of interest ___none

if eligible, why?: age

comments
- banco run along S. wall under porch
- porch: shed rf. w/ drop'd flat ceiling

owner Neli Rael
her father-in-law: Apolonio Rael

associated buildings? ___yes
what type?

if inventoried, list ID nos.

see back? ___yes

ADDRESS: 613 W. San Francisco **HIST. SURVEY #:** 168

(OD = Out of District; M = Moved
DEM = Demolished; N/A = not a building)

NAME:

CITY SURVEY

Area #: 7 Signif. Status: S

(S = Significant; C = Contributing; NC = Noncontributing

REGISTER STATUS (Individual Nominations)

National: N State: N State #: N/A

HSFF: N **HABS:** N

(OSFT = To be in forthcoming 4th edition of Old Santa Fe Today.
Not covered by a more detailed Bulletin article.)

DOCUMENTATION

SFHS Inventory: Y

NR Nomination: N/A SR Nomination: N/A

HSFF Bulletin: N/A HABS Data: N/A

Historic Photos: Museum: Archives:

Modern Photos: MNM: SRC:

Surveys: Floor Plans: Elevations:

Other:

Bibliography:

Comments:

613 W. SAN FRANCISCO

THE ATTACHED SURVEY FORM REFLECTS HISTORIC BUILDING SURVEY WORK THAT WAS COMPLETED DURING APRIL - SEPTEMBER OF 1996. RESULTS OF THE SURVEY AS REFLECTED ON THE ATTACHED HAS NOT BEEN ADOPTED BY THE CITY COUNCIL. IT SHOULD BE CONSIDERED PRELIMINARY FOR PURPOSES OF PLANNING. THIS IS TRUE AS OF 1/97.

PLEASE SEE HEATHER OR MARY FOR MORE INFORMATION OR CLARIFICATION.